
# **ESAB Welding & Cutting Products**









ESAB 1904-2004
A CENTURY OF INNOVATION



# THREE CUTTING METHODS

#### **MECHANICAL**

Saw, Drill, Punch, Shear

CHEMICAL Oxy-Fuel

#### **THERMAL**

Plasma, Laser, Electron Beam





#### WHAT IS A PLASMA ARC?

PLASMA - a fluid part of the blood

- PLASMA an ionized gas (Air)
  - When a gas is heated above 17,000 °F, electrons are free to move. The gas conducts electricity



# THE PLASMA SYSTEM

AIR REGULATOR / FILTER

**Work Clamp** 

**Torch** 




POWER SOURCE/ CONTROL

SPARE PARTS KIT



# GTAW (TIG) ARC






# GTAW (TIG) ARC = OPEN ARC

- Excellent heat source 35,000 °F
- Arc lacks intensity or focus
- Arc lacks needed velocity to blow molten metal from kerf
- Excellent for welding unsuitable for cutting or gouging




#### PLASMA = CONSTRICTED ARC

- Constriction focuses the arc
- Increases arc temperature
- Increases arc voltage
- Flow of gas controls plasma velocity





# TEMPERATURE DIFFERENCE





### THERMAL SOURCE REQUIREMENTS

- High temperature to melt metal
- Highly focused and intense source to make a narrow kerf

High velocity gas stream - to blow the molten metal from the kerf



# **KERF**


The narrow cut or void left by the cutting process






#### DROSS FORMATION

- The molten metal that was blown through the kerf and sticks (welds itself) to the bottom edge of the plate
- Low travel speed easily removed
- High travel speed Very difficult to remove






## CONVENTIONAL TORCH






## **DUAL FLOW TORCH**





#### HIGH FREQUENCY STARTING


- High Frequency (HF) starting requires an arc of about 10,000 volt at 1.5 MHz
- This high voltage arc jumps the electrode to nozzle gap and ionizes a path through the gas
- When the cutting tip touches the work piece the main arc flows through this ionized path
- The PT-31XL torch uses a HF start





### PILOT ARC STARTING

- Pilot arc torches also require High Frequency to ionize the gas in the torch
- A low current (pilot arc) flows through the HF path. The plasma gas(air) blows this arc through the nozzle
- When the pilot arc comes close enough to the work piece the main cutting arc transfers and takes the place of the pilot arc
- Advantage The cutting tip does not have to touch the work piece resulting in longer life



The PT-25, 26, 27 and PT-121 torches use a *PILOT ARC* start.



### PILOT ARC

 After two seconds of \*preflow the HF energizes and the PILOT ARC fires



(Click on image to play video)




\* Preflow: The gas (air) flow prior to the High Frequency and Pilot Arc



# **OPERATING TIPS**

### The Do's and Don'ts






PT-25 / PT-26 / PT-27



## TORCH SETUP

 With the POWER turned "OFF" - Check the torch consumables for wear and proper assembly







#### AIR SETUP

 With the POWER turned "ON" and the AIR CHECK switch in the "ON" position - set the air pressure per the instruction literature (usually 65-75 psi.)







## AIR SUPPLY

- Contaminated air supply will shorten electrode and nozzle life.
- Check filter bowl for water or oil.
- An additional air filter/dryer may be necessary. Available for less than \$100.









## WHEN TO CHANGE CONSUMABLES

 Cut speed and quality will deteriorate when the nozzle (tip) or electrode become damaged.








# TECHNIQUE

(Click on image to play video)





#### PLASMA TORCH ARC STARTING



PT-25, 26, 27

#### **PILOT ARC - START**

PLACE TIP 1/4" ABOVE PLATE - DO NOT TOUCH PLATE!




# **EDGE STARTS**

Always start at the edge With some metal under the tip



PT-34, PT-31XL




PT-25, PT-26 or PT-27



### **EDGE STARTS**

 NEVER PLACE THE TIP OVER THE EDGE -WITHOUT METAL UNDER THE TIP



PT-31XL, PT-34



PT-25, 26 or PT-27



### PIERCE STARTS

 Never pierce with the torch in the vertical position and the tip touching the plate

PT-25 PT-26 / PT-27





## PIERCE STARTS

# ANGLE TORCH TO BLOW MOLTEN METAL AWAY FROM CUTTING TIP AND TORCH HEAD







#### **Pierce Starts**

- Angle torch to blow molten metal away from cutting tip and torch head
- NEVER pierce with the torch in the vertical position







(Click on image to play video)




## **DRAG CUTTING**

- Hold the tip against a straight edge
- Follow a template for irregular shapes

(Click on image to play video)









# DRAG CUTTING TECHNIQUE





- You can drag the PT-31XL or PT-34 torch on the plate
- Hold the tip against a straight edge
- Follow a template for irregular shapes



# **CUTTING WITH A CONSTANT STAND OFF**

- Hold the torch nozzle approximately 5mm above the plate
- Torch angled of 5° to
   15° to plate surface

(Click on image to play video)





#### DRAG CUTTING WITH STAND OFF GUIDE

Use stand off guide to optimize consumable life

(Click on image to play video)










# PLASMA ARC GOUGING





# PLASMA GOUGES



AL

CS

SS




# **Plasma Gouging**

- Torch angled 30° to plate surface
- Arc washes the surface instead of cutting

(Click on image to play video)








# PLASMA CUTTING vs GOUGING

#### **Plasma cutting**

- Torch held 90° to plate surface
- Smaller orifice produces highly constricted arc
- High arc force produces cut



#### Plasma gouging


- Torch angled 30° to plate surface
- Larger orifice produces softer wider arc
- Arc washes the surface instead of cutting





#### PLASMA GOUGING vs CARBON ARC GOUGING

- Lower fume levels
- Lower noise levels
- High quality surface
- Lower cost





# **ESAB Welding & Cutting Products**

# THE END







ESAB 1904-2004 A CENTURY OF INNOVATION

