# Metal Cutting - 4

Assoc Prof Zainal Abidin Ahmad

Dept. of Manufacturing & Industrial Engineering Faculty of Mechanical Engineering Universiti Teknologi Malaysia



## Content

## 6. Proses Melarik

- 6.1 Pengenalan
- 6.2 Pelbagai operasi pemesinan menggunakan mesin larik
- 6.3 Bahagian mesin larik
- 6.4 Jenis mesin larik
- 6.5 Alat pemotong mesin larik
- 6.6 Peranti pemegang bendakerja
- 6.7 Keadaan pemotongan


## 6.1 Pengenalan

### What is turning?

- Turning is the machining operation that produces cylindrical parts. In its basic form, it can be defined as the machining of an external surface:
  - with the workpiece rotating,
  - with a single-point cutting tool, and
  - with the cutting tool feeding parallel to the axis of the workpiece and at a distance that will remove the outer surface of the work.
- Taper turning is practically the same, except that the cutter path is at an angle to the work axis. Similarly, in contour turning, the distance of the cutter from the work axis is varied to produce the desired shape.
- Even though a single-point tool is specified, this does not exclude multiple-tool setups, which are often employed in turning. In such setups, each tool operates independently as a single-point cutter.

Assoc Prof Zainal Abidin Ahmar

UTM 2006



(a) Schematic illustration of a turning operation showing depth of cut, d, and feed, f. Cutting speed is the surface speed of the workpiece and the Fc, is the cutting force, Ft is the thrust or feed force (in the direction of feed, Fr is the radial force that tends to push the tool away from the workpiece being machined.


Assoc Prof Zainal Abidin Ahmar

#### Adjustable cutting factors in turning


The three primary factors in any basic turning operation are speed, feed, and depth of cut. Other factors such as kind of material and type of tool have a large influence, of course, but these three are the ones the operator can change by adjusting the controls, right at the machine.

- **Speed,** always refers to the spindle and the workpiece. When it is stated in revolutions per minute (rpm) it tells their rotating speed. But the important figure for a particular turning operation is the surface speed, or the speed at which the workpiece material is moving past the cutting tool. It is simply the product of the rotating speed times the circumference (in meter) of the workpiece before the cut is started. It is expressed in surface meter per minute (m/min), and it refers only to the workpiece. Every different diameter on a workpiece will have a different cutting speed, even though the rotating speed (N) remains the same.
- *Feed,* always refers to the cutting tool, and it is the rate at which the tool advances along its cutting path. On most power-fed lathes, the feed rate is directly related to the spindle speed and is expressed in mm (of tool advance) per revolution ( of the spindle), or mm/rev.
- Depth of Cut, is practically self explanatory. It is the thickness of the layer being removed from the workpiece or the distance from the uncut surface of the work to the cut surface, expressed in mm. It is important to note, though, that the diameter of the workpiece is reduced by two times the depth of cut because this layer is being removed from both sides of the work.

Assoc Prof Zainal Abidin Ahmar'




### 6.2 Pelbagai operasi pemesinan menggunakan mesin larik



#### Cylindrical turning


The tool moves parallel to the axis of the workpiece The feed/rev is kept small to improve the surface finish




#### Screw cutting

The tool moves parallel to the axis of the workpiece The feed/rev is coarse and equals the lead of the thread being cut: Lead = pitch  $\times$  number of starts


#### Assoc Prof Zainal Abidin Ahmar'





Conical (taper) turning The tool moves at an angle to the axis of the workpiece The feed/rev is kept small to improve the surface finish




Surfacing (facing) The tool moves along a path perpendicular (90°) to the axis of the workpiece The feed/rev is kept small to improve the finish










Assoc Prof Zainal Abidin Ahmar















## 6.4 Jenis Mesin Larik

## Turret lathe

The turret lathe is a form of metal cutting lathe that is used for short production runs of parts. The "turret" part of the name is a special style of tailstock that can hold up to 6 tools with straight shanks. By pushing the handlever forward, the tool is moved toward the workpiece held in the headstock, eventually making contact and cutting or forming the part. On the return stroke, the tool is retracted and indexed to the next tool held in the turret. In this way, a sequence of operations can be performed on a part without switching tools with each operation. (That is, different tools can be shifted into position without the need to unscrew one and screw in another). Each tool can be set for a different travel by a stop screw located at the far right of the turret.

Assoc Prof Zainal Abidin Ahmar






Turret lathe tooling set-up for producing part shown. Numbers in circles indicate the sequence of operation from 1 to 9. Operation 3 is a combined operation. The roll turner is turning surface F while tool 3 on the square post is turning surface B.


Assoc Prof Zainal Abidin Ahmar

UTM 2006




Using a disk turret which can hold 12 to 14 tools for a variety of internal and external machining operations

Assoc Prof Zainal Abidin Ahmar'




Assoc Prof Zainal Abidin Ahmar'

UTM 2006




Assoc Prof Zainal Abidin Ahmar'






Assoc Prof Zainal Abidin Ahmar'




Assoc Prof Zainal Abidin Ahmar'




		н	igh-Speed	Steel			Ca	rbide (Inse	·ts)	
Material	Back Rake	Side Rake	End Relief	Side Relief	Side and End Cutting Edge	Back Rake	Side Rake	End Relief	Side Relief	Side and End Cutting Edge
Aluminum and magnesium alloys	20	15	12	10	5	0	5	5	5	15
Copper alloys	5	10	8	8	5	0	5	5	5	15
Steels	10	12	5	5	15	-5	-5	5	5	15
Stainless steels	5	8-10	5	5	15	-5-0	-5-5	5	5	15
High-temperature alloys	0	10	5	5	15	5	0	5	5	45
Refractory alloys	0	20	5	5	5	0	0	5	5	15
Titanium alloys	0	5	5	5	15	-5	- 5	5	5	5
Cast irons	5	10	5	5	15	-5	- 5	5	5	15
Thermoplastics	0	0	20-30	15-20	10	0	0	20-30	15-20	10
Thermosets	0	0	20-30	15-20	10	0	15	5	5	15


Assoc Prof Zainal Abidin Ahmar'

UTM 2006




Assoc Prof Zainal Abidin Ahmar'






Assoc Prof Zainal Abidin Ahmar




(a) Schematic illustrations of a draw-in type collet. The workpiece is placed in the collet hole, and the conical surfaces of the collet are forced inward by pulling it with a draw bar into the sleeve. (b) A push-out type collet.



Assoc Prof Zainal Abic FIGURE 23-37 Several types of lathe collets. (Courtesy of South Bend Lathe.)



### Summary of Turning Parameters & Formulas N = Rotational speed of the workpiece, rpm f = Feed, mm/rev or in/rev



lote: The units given are those that are commonly used; however, appropriate units must be sed and checked in the formulas.

Assoc Prof Zainal Abidin Ahmar'

UTM 2006

General Recommendations for Turning Operations										
		General-p	urpose starting	conditions	Range for roughing and finishing					
Workpiece material	Cutting tool	Depth of cut, mm (in.)	Feed, mm/rev (in./rev)	Cutting speed, m/min (ft/min)	Depth of cut, mm (in.)	Feed, mm/rev (in./rev)	Cutting speed, m/min (ft/min)			
Low-C and	Uncoated	1.5-6.3	0.35	90	0.5-7.6	0.15-1.1	60-135			
free machining	carbide	(0.06 - 0.25)	(0.014)	(300)	(0.02-0.30)	(0.006-0.045)	(200-450)			
steels	Ceramic-			245-275		( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	120-425			
	coated carbide			(800-900)			(400-1400)			
	Triple-coated	(. <b>*</b> .)		185-200			90-245			
	carbide			(600-650)			(300-800)			
	TiN-coated			105-150			60-230			
	carbide			(350-500)			(200-750)			
	Al <sub>2</sub> O <sub>3</sub> ceramic		0.25	395-440			365-550			
			(0.010)	(1300 - 1450)			(1200 - 1800)			
	Cermet		0.30	215-290			105-455			
			(0.012)	(700-950)			(350-1500)			
Medium and	Uncoated	1.2-4.0	0.30	75	2.5-7.6	0.15-0.75	45-120			
high-C steels	carbide	(0.05 - 0.20)	(0.012)	(250)	(0.10-0.30)	(0.006 - 0.03)	(150-400)			
	Ceramic-			185-230		+	120-410			
	conted carbide			(600-750)			(400-1350)			
	Triple-coated			120-150			75-215			
	carbide			(400-500)			(250-700)			
	TiN-coated carbide			90-200	1 H C	*	45-215			
				(300-650)			(150-700)			
	Al <sub>2</sub> O <sub>3</sub> ceramic		0.25	335	(e) (		245-455			
			(0.010)	(1100)			(800-1500)			
	Cermet		0.25	170-245		÷	105-305			
			(0.010)	(550-800)			(350-1000)			
Cast iroa, gray	Uncoated	1.25-6.3	0.32	90 (300)	0.4-12.7	0.1-0.75	75-185			
	carbide	(0.05 - 0.25)	(0.013)		(0.015-0.5)	(0.004 - 0.03)	(250-600)			
	Ceramic-		2.42	200	3. C		120-365			
	coated carbide			(650)			(400-1200)			
	TiN-coated		0.00	90-135			60-215			
	carbide			(300-450)			(200-700)			
	Al <sub>2</sub> O <sub>3</sub> ceramic		0.25	455-490			365-855			
			(0.010)	(1500-1600)			(1200 - 2800)			
	SiN ceramic		0.32	730			200-990			
			(0.013)	(2400)			(650-3250			

Assoc Prof Zainal Abidin Ahmar