



Figure 4.6 Photograph of stair treads with painted nosing.

TABLE 4.3 Site Survey for Compliance with the Americans with Disabilities Act

-
1. Is there an adequate number of accessible parking spaces designated?
 2. Do the designated accessible parking spaces meet design minimums?
 3. Is there 1 van-accessible space for every 8 accessible spaces, or are all spaces consistent with the universal parking space design?
 4. Are accessible spaces marked using the international symbol of accessibility?
 5. Are van spaces marked "Van Accessible"?
 6. Is there at least one accessible route allowing access to all public facilities?
 7. Are depressed curbs provided on the accessible route?
 8. Do ramps meet ADA minimums (1:12 slope or less, 36 in wide, 30-in maximum rise, level landing every 30 ft, adequate landing size)?
 9. Are overhead and wall clearances adequate?
 10. Are surfaces nonslip?
 11. Are minor changes in grade beveled to minimize the risk of trip or obstruction?
 12. Are handrails provided where appropriate?
 13. Are textural or audible signals provided where necessary?
-