

SHARING CONSERVATION DECISIONS

Figure 3. Cross-section before and after reconstruction.




Figure 4. Basement (a) before, and (b) after restoration. Photo Milijana Okilj.

